

Name of work :- Replacing damaged items of RMU's as per service report of imperial engineering company

File no. ED1/2237/21

sl.no.	Nature of work	Quantity	Rate Per unit	Total Amount
1	Supply of PCB card for ring switches(sl.no. 997012,997014,997007,997024(2no's),997022,997021,997023)	8 no's	5500	44000
2	Supply of pcb card for circuit breaker(sl.no.997015,997014(2no's),997007)	4 no's	6500	26000
3	supply of 12 V, 26 AH batteries(sl.no. 997024,997021,997023,997007,997014	12 no's	4200	50400
4	supply of RMU series bushes(sl.no. 1VYN040117000957- 2NO'S)	2 no's	9000	18000
5	supply of SF6 gas for 1 CTC RMU(sl.no. 1VYN040117000957- LS)	LS	17500	17500
6	Service charge per day	3 days	22500	67500
	Total sum			223400
	Tax @ 18%			40212
	Total Estimate			263612


SHEMEER.N
Assistant Engineer
Section-1
Electricity Department
Thrissur Corporation